This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents *will not* correct images, please do not report the images to the Image Problem Mailbox.


43a
26
20
40
61
22
32
36
30
60
66
65
21
25
15
14
13
62
12b
10
1
12
2
3
12a

FIG. 1


43a
40
26
32
36
66
20
61
30
65
22
25
60
21
14
62
15
13
12b
1
12
10
2
3
12a

FIG. 2



FIG. 3



FIG. 3a


62
65
66
32
40
30
3
60
43a
43b-44b
26
43
33
44
44a-51
2
61
50
20
52
25
14
22
15
12
21
13
12b
12a
1

FIG. 4



FIG. 4a


3
62
65
66
40
47
41
30
60
42
47
61
43b-44b
26
50
20
14
25
52
44a-51
44
33
43
43a
22
2
15
12
21
13
12a
12b
1

FIG. 5



FIG. 5a


3
62
65
66
32
36
60
30
31
40
31
43b-44b
26
20
61
14
25
52
50
45
33
43
43a
44a-51
44
22
2
15
12
21
13
12a
12b
1

FIG. 6



FIG. 6a


14
25
52
50
45
20
61
3
60
65
66
62
32
36
40
30
31
26
43b-44b
21
22
15
13
12b
12
12a
1
2
44
44a-51
33
43
43a

FIG. 7



FIG. 7a



FIG. 7b


88
OPERATOR CONTROL PANEL
USER CONTROL PANEL
90
INCLINATION SPEED CONTROL
PE
75
MAIN ELECTRICAL PANEL
ACTUATORS ELECTRONIC CONTROL
ELECTRONIC SPEED VARIATION
85
UH
HYDRAULIC UNIT
ACTUATOR MOTOR PUMP
HYDRAULIC MOTOR PUMP
80
70
DIRECTIONAL VALVES
V1
V2
V3
HYDRAULIC MOTOR
42
TREADMILL BELT DRIVING
12
50
45
ARM ACTUATOR
CHASSIS ACTUATOR
INCLINATION ACTUATOR

FIG. 8



FIG. 9



FIG. 9a



FIG. 9B